TECHNICAL SYSTEM AUDIT REPORT

SUMMARY INFORMATION PROJECT NAME: Cornell-Dubilier Superfund Site PROPERTY ADDRESS: 3. DATE(S) OF QC FIELD AUDIT PHONE No. 5. PERSONNEL ON-SITE **NAME** REPRESENTING **PHONE** 972-407-1686 913-407-1363 973-407-1146 914-798-37/2 **AUDITOR'S COMMENTS** 7. WEATHER CONDITIONS PARTLY CLOUDY CLOUDY (RAIN) DRIZZLE SNOW SLEET **SUNNY** PARTLY SUNNY WIND DIRECTION VORIABLE TEMPERATURE FIELD INSTRUMENTS (ONLY MARK THE INSTRUMENTS THAT WERE REQUIRED FOR THIS SAMPLING/MEASUREMENT EVENT) MINI RAE 3000 WAS INSTRUMENT RESPONSE/CALIBRATION CHECKED AND RECORDED? Yes A) MINIRAE 10.6 eV PHOTOIONIZATION DETECTOR B) OTHERS:

TECHNICAL SYSTEM AUDIT REPORT

COMMENTS:	
FIELD MEASUREMENT REQUIREMENTS	
10. WERE THE REQUIREMENTS CONTAINED IN THE WORK PLAN, FSP, QAPP, AND SOPS FOLLOWED?	
11. WERE THE PROPER SAMPLE LOCATIONS CHOSEN? YES (FOP 4/11/11)	
12. WERE THE REQUIRED NUMBER OF QC MEASUREMENTS COLLECTED? YES CAUSING	
SAMPLA PROCESSING)	٤
13. WERE THE REQUIRED FIELD NOTES TAKEN (e.g., DATA SHEETS, MAPS, ETC.)? YE'S	<u>.</u>
in First (4-11-11 FOR) and during symple progression	
14. WERE THE REQUIRED PHOTOGRAPHS TAKEN? YES +	
15. COMMENTS:	r
SOIL/BUILDING MATERIAL SAMPLE INFORMATION	
16. WHAT MATRIX WAS SAMPLED? Road Sedment	
17. WERE THE REQUIREMENTS CONTAINED IN THE WORK PLAN, FSP, QAPP, AND SOPS FOLLOWED? YES ROLLING WHARKET POLICE (NEW WARKET POLICE)	dredging area)
18. WERE THE REQUIRED FIELD NOTES TAKEN (e.g., DATA SHEETS, MAPS, ETC.)? YES	эмаря, У
19. WERE THE REQUIRED PHOTOGRAPHS TAKEN? YES	
20. WHAT TYPE OF SAMPLING EQUIPMENT WAS USED? VIbralore Sampler USING	
20. WHAT TYPE OF SAMPLING EQUIPMENT WAS USED? VIbratore Sampler USING STEEL OWITER barrel with clean Lexan Liver. Stices sampled using S	is tubes, SS
21. WHAT MATERIAL WAS THE SAMPLING EQUIPMENT MADE OF?	bowls and SS
Page 2 of 6	epoons (discrete